

Page 1 Of 3

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : \_\_\_\_\_ Signature : \_\_\_\_\_

**\*\* Delay Codes Legend \*\***

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan

\*\* Record Time Daily \*\* Delays

[illegible]

**\*\* IMPORTANT NOTICE \*\***

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



**IP7\_037450**

CREW: 81

WORK ORDER TYPE: MODIFICATIONS

02-60456-56

ISSUE DATE 01/06/11

Page 2 Of 3

## \*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1 18656	GASKET MATERIAL, RUBBER	S 272819	02/16/04	SF	72	0	72
2 50622	ROD, ALLTHREAD	S 272819	02/16/04	EA	2	0	2
3 50638	ROD, ALLTHREAD	S 272822	02/16/04	EA	4	0	4
4 54209	BANDING, MATERIAL	S 272819	02/16/04	RL	1	0	1
5 54210	BANDING, CLIP	S 272819	02/16/04	EA	6	0	6

IP7\_037451

CREW: 81

WORK ORDER TYPE: MODIFICATIONS

02-60456-56

ISSUE DATE 01/06/11

Page 3 Of 3

**\*\* Work Order Tools List \*\***

Ln	Tool No	Noun Qualifier	Measure 1	Measure 2	Measure 3	Rqd
1	7265	BANDER, TENSIONER	STRAPPING			1

IP7\_037452